

**OFFICE: EXECUTIVE ENGINEER COSTRUCTION DIVISION NO.1.PWD
(B&R)Br. AMRITSAR.**

PHONE :-0183- 2564793

email- xenc1amritsar@yahoo.com

To

Managing Director,
Baba Deep Singh Public School,
Village Dehra Sahib Distt Tarn Taran.

No **245** Dated **03/06/2021**

Sub:- School Building Safety Certificate for the year 2021-22(31.03.2022)


Ref:- Your Letter No.BDSPS/02/2021 Dated.10.05.2021

The Sub Divisional Engineer, Construction Sub Division Tarn Taran vide his office Letter No.42 Dated 31.05.2021 has reported this office that **Baba Deep Singh Public School,Village Dehra Sahib Distt Tarn Taran** has been inspected and found the same structurally safe and fit for human inhabitation for the year 2021-22. **(31.03.2022)**

DA/ Performa in two parts


Endst. No.

Dated.\


Executive Engineer,
Construction Division No.1,
PWD(B&R) Br. Amritsar.

A copy of the above is forward to Sub Divisional Engineer,Construction Sub Division Tarn Taran with ref. to his office letter No 42 dated 31.05.2021 for information.

DA/x


Executive Engineer,
Construction Division No.1,
PWD(B&R) Br. Amritsar.

PROFORMA FOR THE SAFETY CERTIFICATE OF SCHOOL/COLLEGE BUILDING

(Part-I)

(To be filled by the Head of School Institute)

| | | |
|-----|---|--|
| 1. | Name of the School/College | BABA DEEP SINGH PUBLIC SCHOOL VILL DEHRA SAHIB DISTRICT TARN TARAN |
| 2. | Location | VILLAGE DEHRA SAHIB Distt Tarn Taran |
| 3. | Plot Area | 11283.28 Sqyd 101549.25 sft. |
| 4. | Plinth Area | 3622.22 Sqyd 32600 sft. |
| 5. | Number of Storey's | Double |
| 6. | Area of construed part of the building | 2355.55 Sqyd or 32600 sft. |
| 7. | If the building has been constructed under the supervision of the qualified engineer, the following details may be given :- | |
| a) | Name of Engineer with qualification | Enr. Bishampit Singh (Arch. Civil Engineer) |
| b) | Address of the Engineer | Tarn Taran |
| c) | if structural drawing used in the construction , if available | |
| d) | Ar. Gaganbeer Singh | |
| 8. | whether the building has been constructed for the purpose of | School |
| a) | School/College | Yes/No |
| b) | Residential purpose and used for a school | Yes/No |
| 9. | Materials used for Roofs | Cemant and Concreate |
| a) | R.C.C. Slabs | Yes |
| b) | R.S. Joists & Battons | No |
| c) | Wooden Joints and Bottom | Nos |
| 10. | Materials used for Walls | 1 st Class BB Work |
| a) | Mud Mortor | Yes/No |
| b) | Cement Mortor | Yes/No |
| c) | Line Mortor | Yes/No |

| | | |
|-----|--|-------------------|
| 11. | Flooring | C.C. Florry/Tiles |
| a) | Conglomerate | Yes/No |
| b) | Terrace | Yes/No |
| c) | Brick Paving | Yes/No |
| 12. | A detailed drawing indication the doors along with windows and location fitting and windows is attached | Enclosed |
| a) | For Fire Safety | Yes/No |
| b) | Whether the width of the staircase is 1.5 mtr. | Yes/No |
| c) | Whether School building is free from inflammable & toxic material | Yes/No |
| d) | Whether cooking of food is done at a Safe Place | Yes/No |
| e) | Whether any Thatch or combustible mate Has been used | Yes/No |
| 14. | Requirement for fire protection Arrangements under NB-Part-IV | |
| a) | Whether Hose Real Provided | Yes/No |
| c) | Whether Automatic sprinkler provided | Yes/No |
| d) | Whether underground static water storage tank of capacity | Yes/No |
| e) | whether over head tank of capacity 10000 ltr exists (in case of hose real) 20000 ltr . | Yes/No |
| f) | Whether one eclectic and one diesel pump of 3 Kg/Cum pressure of capacity 1620 LPM, one electric pump of Compactly 180 LPK exist near underground static tank. | Yes/No |
| g) | Whether pump 3 Kg/cum pressure & 450/500 LPM Exist near over head tank | Yes/No |

W.S.
Sub Divisional Engineer
Construction Sub Division
PWD B&R, Tarn Taran

Gurpartap Singh
 Signature of the Head of
 School & Collges/Institute

Managing Director
Baba Deep Singh Public School
Dehra Sahib (Tarn Taran)

(Baba Deep Singh Public School, Vill. Dehra Sahib)
Distt. Tarn Taran.

**PERFORMA FOR THE SAFTY CERTIFICATE OF SCHOOL/COLLEGE
BUILDING**

(Part II)

(To be filled by the SDE of PWD (B&R) Department)

- a) I have visited the above mentioned School/College on date 17-05-2022 and have visually inspected it from all angles of safety and find it fit for normal use a school/College building .,
- b) In case any addition/alteration or expansion and modification to this building I to be carried out the same be carried out under the supervision of a qualified Engineer an this certificate may be re-obtained after the completion from the undersigned.
- c) In case the building is affected by flood, or if there is settlement of walls foundation. or sagging of roofs etc. immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) This building can be safely occupied for normal use upto (indicate upto which it can be used upto...31.03.2022)

Pur
J.E

VKJ
Sub Divisional Engineer
Construction Sub Division
PWD B&R, Tarn Taran